

TECHNICAL SHEET

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

export@sirsafety.com www.sirsafety.com

Quality Management System Certificate UNI EN ISO 9001:2015

Name: FUSION BERMUDA MAS.

Code: MC1722Z9

MC17 CLOTHING - FUSION SERIES

Description

Bermudas in Massaua 100% cotton, weight 280 g/m .

Fly with zipper and tack button, two front pockets and coin pocket on the right, ruler pocket with tool holder on the right, back right pocket with flap and Velcro, back left pocket with Velcro fastening, multi-functional utility pocket with flap and Velcro, with pen holder and phone pocket. Reinforcement bar tacks in contrasting colour

The Fusion series is:

- made of a strong fabric, suitable to the most demanding jobs;

- resistant, practical and functional andfeatures a wide range of accessories, multifunctional utility pockets and wear-resistant reinforcements in technical fabric;

- equipped with details such as the reinforced runners and jointed double seams in contrasting colour, which assure long-lasting use and high quality.

Protection against risks of dirt and detrimental actions of slight damage.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments. V@Á æ}Á¢c∿¦}æ∱Áæà¦æ∕≨ÁJÒSUË/ÒÝí ÁĴæ}åæåÁ∓€€Á

Category	Colours	Available Sizes
I	BLACK	38 - 70
Quantity/Carton	EC Standards	Important Information
		Metalworking Industry, Construction, Logistics, Transport, Agriculture and Maintenance
50		Store in a cool, dry place, away from heat sources and away from light. Before each use, carry out a visual check to ensure that the device is in perfect condition, undamaged and clean, and replace it if it is not intact.
		Follow the recommended washing instructions.
Dexterity		Storage and cleaning Data retrieval failed for the subreport,